


Setup:

Data Entry

1. Place the Data Entry Operator terminal between the Main Laptop and the Controller.



2. Connect a Blue Ethernet cable and a long 4-pin cable from the Data Entry Operator terminal to the Data ports on the Processor.




Video Monitor

1. Place the Sharp Video Monitor where all the Tech Panel can view it.
2. Plug the RCA end of the Monitor Cable into the cable from the Sharp Video Monitor. Plug the BNC end of the Monitor Cable into the Processor.



3. Plug the Camera Cable into the Camera BNC on the Processor. Use adaptors if necessary.



4. Plug the Monitor into a UPS plug with backup power. Use the short extension cord if necessary.

Teardown:

Data Entry

1. Disconnect the Blue Ethernet cable and a long 4-pin cable from the Data Entry Operator terminal and the Processor. Wrap and place both cables in Processor container (wrapped around the Black tape).
2. Place the Data Entry Operator terminal in the center slot of the Processor shipping container.

Video Monitor

1. Disconnect Monitor cable from the Video Monitor and the Processor. Wrap and place in the smallest (Cable) shipping container.
2. Disconnect Camera cable from the video feed and the Processor. Wrap and place in the smallest (Cable) shipping container.
3. Place the Sharp Monitor in the rear slot of the Processor shipping container. The monitor goes in upside-down, with the foot overlapping the top of the foam in the case. Do **not** disconnect the power brick from the monitor. The power brick goes in the hole next to the Date Entry Terminal. The short extension cord goes with the monitor.

